PR001
03-Mar-16

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Falling, Rolling or Sliding Rock /Materl	02/26/2016 08:35 AM	02/26/2016 10:04 AM	1

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Lonestar Prospects Ltd.	Vista Sand	RJS Holdings LLC; MWR Holdings LLC

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Granbury	Hood	TX	41-04430	NO

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
CONSTRUCTION SAND & GRAVEL M	156	0	59	26	71

12. Contractor Name:	13. Union	14. Contractor ID Number:
Powell Transportation Company	NO	

15. Contractor Address: a) City	b) County	c) State	d) Zip Code
Columbia	Marion	MS	39429

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
4				4

17. Number of Persons in Mine at Time of Accident:
a) Mine Employees: 67 b) Contractor Employees: 4

18. Number of Persons Unaccounted For:
a) Mine Employees: 0 b) Contractor Employees: 0

19) Location of Accident
- [ ] 01-Underground
- [x] 03-Open Pit
- [ ] 07-Advance Mining
- [ ] 30-Mill/Prep Plant
- [ ] Other (specify)
- [ ] 02-Surface at Underground
- [ ] 06-Dredge Mining
- [ ] 08-Retreat Mining
- [ ] 99-Office Facility

20. Mining Height: Feet Inches

21. Nonfatal Injuries: 0

22. Fatal Injuries: 1

23. Victim Information : a) Name: Elvin T. Terrell b) Age: 61

c) Regular Job Title: Truck Driver
d) Activity at Time of Accident: Unloading pipe from truck
[x] Contractor Employee

24. Experience :

	Years	Weeks	Days
a) Total:	12	7	4
b) at the mine:	1		
c) at activity (23d)	12	7	4
d) with Contractor	3	38	2

25. Autopsy Performed: YES **If Yes, Location:** Tarrent County

26. Mine Telephone No.: (817) 279-1660

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was the driver of the first of four trucks to be unloaded at the mine near the primary plant. The trucks were loaded with 9 sections each of 26"OD diameter polyurethane pipe with each section 50' long and weighing approximately 1732 pounds. The pipe was stacked in three layers of three pieces each. The driver unsecured the load and the first two sections of pipe off the top layer were removed. The driver was observed walking around the truck when a section of pipe rolled off the trailer and landed on the driver.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:
Volvo	D13

30. District:	32. Field Office:	33. Event Number:
M5000 South Central	Dallas TX	6734017

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Homer Pricer	Elwood M. Burriss	02/26/2016	09:04 AM

36. Type of Report:	37. Name of Preparer and Date Prepared:	Date
Initial	Mac Burriss	03/01/2016

38. Reason For Amendment: