

PR001
05-Jan-11

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident 12/29/2010 02:00 PM		4. Date/Time of Death 12/29/2010 04:34 PM		5. Fatal Case No 24		
6. Mine Information :										
a) Mining Company Name Martinez Stone			b) Mine Name Martinez Stone			c) Parent of Mining Company				
7. Mine Location :		a) City San Saba		b) County San Saba		c) State TX		8. Mine ID Number: 41-04848		9. Union: NO
10. Primary Mineral Mined: DIMENSION SANDSTONE MINING		11. Number of Mine Employees:		a) Total 6	b) Underground	c) Open Pit/Quarry 6	d) Mill/Prep Plant		e) Other	
12. Contractor Name:					13. Union		14. Contractor ID Number:			
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 5		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident								20. Mining Height:		
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet Inches		
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :		a) Name Jesus M. Martinez			b) Age 41					
c) Regular Job Title: Laborer/Mechanic		d) Activity at Time of Accident: Skid-steer maintenance			<input checked="" type="checkbox"/> Mine Employee					
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total: 4		b) at the mine: 0 5 3		c) at activity (23d) 0 5 3		d) with Contractor				
25. Autopsy Performed: If Yes, Location NO					26. Mine Telephone No.: (325) 248-1141					

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was standing under the raised the forks of a skid-steer loader while replacing a hydraulic cylinder on the machine. The forks lowered pinning him against the frame of the loader.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Gehl		29. Model: 6640	
30. District: M5000 South Central		32. Field Office: San Antonio TX	
34. Accident Investigator: Ralph Rodriguez		33. Event Number: 6548120	
35. MSHA Person Notified: Elwood M. Burriss		Date 12/29/2010	
36. Type of Report: Amended		Time 07:38 P	
37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>		Date 01/05/2011	
38. Reason For Amendment: Amendment No. 1-- Items 23 (c) , 24 (a), (b), (c) , 27			