

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 05/14/2014 02:15 PM		4. Date/Time of Death 05/14/2014 04:12 PM		5. Fatal Case No 6				
6. Mine Information :												
a) Mining Company Name M-Class Mining LLC			b) Mine Name MC#1 Mine			c) Parent of Mining Company Coalfield Transport Inc						
7. Mine Location :		a) City Macedonia		b) County Franklin		c) State IL		8. Mine ID Number: 11-03189		9. Union: NO		
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND			11. Number of Mine Employees:		a) Total 330	b) Underground 275	c) Open Pit/Quarry		d) Mill/Prep Plant 55	e) Other		
12. Contractor Name:						13. Union		14. Contractor ID Number:				
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code				
16. Number of Contractor Employees:		a) Total	b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:							
a) Mine Employees: 131		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0					
19) Location of Accident									20. Mining Height:			
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches		
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility				9	3		
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1										
23. Victim Information :				a) Name William-Daniel H. Payne		b) Age 25						
c) Regular Job Title: Roof Bolter			d) Activity at Time of Accident: Tramming Roof Bolter				<input checked="" type="checkbox"/> Mine Employee					
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days				
a) Total:	2	15	0	b) at the mine:	2	15	0	c) at activity (23d)	2	15	0	d) with Contractor
25. Autopsy Performed: If Yes, Location YES Franklin County Hospital								26. Mine Telephone No.: (618) 435-9426				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On Wednesday, May 14, 2014, at approximately 2:15 p.m., a roof bolter operator was fatally injured. The victim was pinned between a roof bolting machine and the coal rib as he was walking along side of the roof bolter. This accident occurred on the roadway to the Viking Portal No. 1 longwall tailgate section. The section equipment was in the process of being removed from the longwall set up rooms.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Fletcher			29. Model: DDR-17			
30. District: C0800 Vincennes		32. Field Office: Marion IL			33. Event Number: 4254436	
34. Accident Investigator: Harry Wilcox			35. MSHA Person Notified: Anthony DiLorenzo		Date 05/14/2014	Time 04:01 PM
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Harry Wilcox			Date 05/14/2014	
38. Reason For Amendment: Update experience and location of autopsy.						