

METAL / NONMETAL Close Call Alert

Limestone - Surface – A dozer operator ran over a parked pickup truck. The pickup driver attempted to drive closer to the dozer instead of parking next to the conveyor and got stuck in the loose gravel. The driver was out of the pickup trying to free it and was motioning the dozer operator when the dozer ran over the truck.



BEST PRACTICES

- **Ensure a travel lane is clear before moving a vehicle. Train miners to not walk or stand in travel lanes.**
- **When backing up, look over your shoulder to eliminate blind spots. When using mirrors, use all available mirrors.**
- **Do not travel long distances in reverse, and when able, turn the vehicle around to drive in a forward direction.**
- **Install "rear viewing" cameras on vehicles.**
- **Sound horns before moving equipment in areas where miners are present.**

