

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Fall of Face, Rib, Pillar or Highwall		3. Date/Time of Accident 10/28/2011 06:27 AM		4. Date/Time of Death 10/28/2011 06:27 AM		5. Fatal Case No 18							
6. Mine Information :															
a) Mining Company Name Armstrong Coal Company Inc			b) Mine Name Equality			c) Parent of Mining Company Armstrong Energy Corporation LLC									
7. Mine Location :		a) City Centertown		b) County Ohio		c) State KY		8. Mine ID Number: 15-19344		9. Union: NO					
10. Primary Mineral Mined: BITUMINOUS			11. Number of Mine Employees:		a) Total 118	b) Underground 0	c) Open Pit/Quarry 110	d) Mill/Prep Plant 7	e) Other 1						
12. Contractor Name: Mine Equipment & Mill Supply Company						13. Union NO		14. Contractor ID Number: CXJ							
15. Contractor Address:		a) City Evansville		b) County Vanderburgh		c) State IN		d) Zip Code 47715							
16. Number of Contractor Employees:		a) Total 14		b) Underground 14		c) Open Pit/Quarry 14		d) Mill/Prep Plant 14		e) Other 14					
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:										
a) Mine Employees: 60		b) Contractor Employees: 8			a) Mine Employees: 0		b) Contractor Employees: 0								
19) Location of Accident									20. Mining Height:						
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches					
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility						15	6					
21. Nonfatal Injuries:			22. Fatal Injuries: 2												
23. Victim Information :															
a) Name Samuel J. Lindsey					b) Age 23										
c) Regular Job Title: Blaster Helper					d) Activity at Time of Accident: Blaster Helper										
<input checked="" type="checkbox"/> Contractor Employee															
24. Experience :															
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days						
a) Total:	0	13	0	b) at the mine:	0	13	0	c) at activity (23d)	0	13	0	d) with Contractor	0	13	0
25. Autopsy Performed: If Yes, Location YES Louisville, KY								26. Mine Telephone No.: (270) 232-9695							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On October 28, 2011 at approximately 6:27 a.m. a certified blaster and blaster helper received fatal injuries at the Equality Mine operated by Armstrong Coal Company. A portion of the highwall failed in the west end of the #11 pit covering the truck and the two miners. A 103(J) Order has been issued and MSHA investigators are on site conducting an investigation.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Ford (Ford Motor Co.)			29. Model: F-350				
30. District: C1000 Madisonville		32. Field Office: Beaver Dam KY			33. Event Number: 4486387		
34. Accident Investigator: William L. Barnwell			35. MSHA Person Notified: Ted Smith			Date 10/28/2011	Time 06:45 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Troy K. Davis				Date	
38. Reason For Amendment:							

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Fall of Face, Rib, Pillar or Highwall		3. Date/Time of Accident 10/28/2011 06:27 AM		4. Date/Time of Death 10/28/2011 06:27 AM		5. Fatal Case No 19											
6. Mine Information :																			
a) Mining Company Name Armstrong Coal Company Inc			b) Mine Name Equality			c) Parent of Mining Company Armstrong Energy Corporation LLC													
7. Mine Location :		a) City Centertown		b) County Ohio		c) State KY		8. Mine ID Number: 15-19344		9. Union: NO									
10. Primary Mineral Mined: BITUMINOUS			11. Number of Mine Employees:		a) Total 118	b) Underground 0	c) Open Pit/Quarry 110	d) Mill/Prep Plant 7	e) Other 1										
12. Contractor Name: Mine Equipment & Mill Supply Company						13. Union NO		14. Contractor ID Number: CXJ											
15. Contractor Address:		a) City Evansville		b) County Vanderburgh		c) State IN		d) Zip Code 47715											
16. Number of Contractor Employees:		a) Total 14		b) Underground 14		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other									
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:														
a) Mine Employees: 60		b) Contractor Employees: 8			a) Mine Employees: 0		b) Contractor Employees: 0												
19) Location of Accident									20. Mining Height:										
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)				Feet	Inches										
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility					15	6										
21. Nonfatal Injuries:		22. Fatal Injuries: 2																	
23. Victim Information :																			
a) Name Darrel A. Winstead					b) Age 47														
c) Regular Job Title: Certified Blaster					d) Activity at Time of Accident: Certified Blaster														
<input checked="" type="checkbox"/> Contractor Employee																			
24. Experience :																			
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days										
a) Total:		2	0	0	b) at the mine:		1	29	0	c) at activity (23d)		1	26	0	d) with Contractor		2	0	0
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.:													
YES Louisville, KY						(270) 232-9695													

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
 On October 28, 2011 at approximately 6:27 a.m. a certified blaster and blaster helper received fatal injuries at the Equality Mine operated by Armstrong Coal Company. A portion of the highwall failed in the west end of the #11 pit covering the truck and the two miners. A 103(J) Order has been issued and MSHA investigators are on site conducting an investigation.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Ford (Ford Motor Co.)			29. Model: F-350		
30. District: C1000 Madisonville		32. Field Office: Beaver Dam KY			33. Event Number: 4486387
34. Accident Investigator: William L. Barnwell			35. MSHA Person Notified: Ted Smith		Date 10/28/2011
					Time 06:45 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Troy K. Davis			
38. Reason For Amendment:					