

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 05/17/2013 01:30 AM		4. Date/Time of Death 05/17/2013 03:40 AM		5. Fatal Case No 7		
6. Mine Information :										
a) Mining Company Name Chevron Mining Inc			b) Mine Name Questa Mine & Mill			c) Parent of Mining Company Chevron Corporation				
7. Mine Location :		a) City Questa		b) County Taos		c) State NM		8. Mine ID Number: 29-01267		9. Union: YES
10. Primary Mineral Mined: MOLYBDENUM ORE MINING			11. Number of Mine Employees:		a) Total 310	b) Underground 122	c) Open Pit/Quarry		d) Mill/Prep Plant 46	e) Other 142
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City			b) County		c) State		d) Zip Code	
16. Number of Contractor Employees:										
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 168		b) Contractor Employees:			a) Mine Employees: 0		b) Contractor Employees:			
19) Location of Accident									20. Mining Height:	
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 04-Dredge Mining	<input type="checkbox"/> 05-Advance Mining	<input type="checkbox"/> 06-Retreat Mining	<input type="checkbox"/> 07-Mill/Prep Plant	<input type="checkbox"/> 08-Office Facility	<input type="checkbox"/> Other (specify)	Feet Inches	
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :				a) Name Issac A. Garcia		b) Age 22				
c) Regular Job Title: Mucker			d) Activity at Time of Accident: Checking derailed ore car				<input checked="" type="checkbox"/> Mine Employee			
24. Experience :	Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days			
a) Total:	0	28	b) at the mine:	0	28	c) at activity (23d)	0	28	d) with Contractor	
25. Autopsy Performed: If Yes, Location YES Albuquerque, NM						26. Mine Telephone No.: (575) 586-7507				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was checking a derailed ore car when he was pinned between it and another ore car.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: ASEA Inc.			29. Model: 10-ton ore car		
30. District: M5000 South Central		32. Field Office: Albuquerque NM			33. Event Number: 6609622
34. Accident Investigator: William D. Odell			35. MSHA Person Notified: Elwood M. Burriss		Date Time 05/17/2013 01:41 A
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>			Date 05/17/2013
38. Reason For Amendment: Amendment No. 1 Items 3, 4, and 35					