

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 09/19/2013 02:00 PM		4. Date/Time of Death 09/19/2013 02:00 PM		5. Fatal Case No 13		
6. Mine Information :										
a) Mining Company Name T. G. Mountain Stone			b) Mine Name Northrup Quarry			c) Parent of Mining Company Jan Tuttle; Charles God				
7. Mine Location :		a) City Monroeton		b) County Bradford		c) State PA		8. Mine ID Number: 36-09526		9. Union: NO
10. Primary Mineral Mined: DIMENSION STONE MINING, N.E.C.			11. Number of Mine Employees:		a) Total 3	b) Underground 0	c) Open Pit/Quarry 3	d) Mill/Prep Plant 0	e) Other 0	
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:										
a) City		b) County			c) State			d) Zip Code		
16. Number of Contractor Employees:										
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 2		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident								20. Mining Height:		
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet Inches		
21. Nonfatal Injuries:			22. Fatal Injuries: 1							
23. Victim Information :										
a) Name Timothy Farr					b) Age 31					
c) Regular Job Title: Laborer				d) Activity at Time of Accident: Operating haul truck			<input checked="" type="checkbox"/> Mine Employee			
24. Experience :										
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days	
a) Total: 14 0 0		b) at the mine: 14 0 0		c) at activity (23d)		14 0 0		d) with Contractor		
25. Autopsy Performed: If Yes, Location YES						26. Mine Telephone No.: (570) 250-6975				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was operating a 2 1/2 ton truck up a steep roadway. He was hauling water tanks on the bed of the truck when the truck overturned on its roof and crushed him.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model: M35A2	
30. District: M2000 Northeastern		32. Field Office: Geneva NY		33. Event Number: 6625406	
34. Accident Investigator: Gary C. Merwine			35. MSHA Person Notified: Rodney L Rice		Date 09/19/2013
					Time 04:12 P
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Mike Harcher <i>MH</i>			Date 09/20/2013
38. Reason For Amendment: Item. No. 23 (b)					