

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 06/04/2014 05:35 AM		4. Date/Time of Death 06/04/2014 05:35 AM		5. Fatal Case No 07		
6. Mine Information :										
a) Mining Company Name Peabody Powder River Mining LLC			b) Mine Name North Antelope Rochelle Mine			c) Parent of Mining Company Peabody Energy				
7. Mine Location :			a) City Wright		b) County Campbell		c) State WY		8. Mine ID Number: 48-01353	9. Union: NO
10. Primary Mineral Mined: BITUMINOUS			11. Number of Mine Employees:	a) Total 1517	b) Underground 0	c) Open Pit/Quarry 850	d) Mill/Prep Plant 126	e) Other 541		
12. Contractor Name: Rogers Construction Inc.						13. Union NO		14. Contractor ID Number: S843		
15. Contractor Address:			a) City Whitewood		b) County Pennington		c) State SD		d) Zip Code 57793	
16. Number of Contractor Employees:			a) Total 280	b) Underground 0	c) Open Pit/Quarry 200	d) Mill/Prep Plant 80	e) Other 0			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 270		b) Contractor Employees: 117			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)				Feet	Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility					75	0	
21. Nonfatal Injuries: 0			22. Fatal Injuries: 1							
23. Victim Information :										
a) Name Joshua L. Wishard					b) Age 25					
c) Regular Job Title: Equipment Operator										
d) Activity at Time of Accident: Removing large rock from crusher <input checked="" type="checkbox"/> Contractor Employee										
24. Experience :										
Years		Weeks		Days		Years		Weeks		Days
a) Total: 24		b) at the mine: 15		3		c) at activity (23d) 19		d) with Contractor 24		
25. Autopsy Performed: YES Campbell County Coroners Office						26. Mine Telephone No.: (307) 464-4891				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

At approximately 05:35 am, on June 4, 2014, a 25 year old contract employee was fatally injured when he was crushed between the hood and the frame of a Metso Horizontal Impact Crusher. The crusher was located on the North Antelope Rochelle Mine at the Rail Loop East Scoria Crusher Pit. MSHA is investigating the accident.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Not listed			29. Model: M005615		
30. District: C0900 Denver		32. Field Office: Gillette WY			33. Event Number: 4268353
34. Accident Investigator: Lois J. Duwenhoegger			35. MSHA Person Notified: Peter Saint		Date 06/04/2014
					Time 05:53 AM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Lois Duwenhoegger			Date 06/05/2014
38. Reason For Amendment:					