

# Preliminary Report of Accident



1. Accident Type: Fatal Injury	2. Accident Classification Fall of Face, Rib, Pillar or Highwall	3. Date/Time of Accident 03/08/2015 09:00 PM	4. Date/Time of Death 03/08/2015 09:45 PM	5. Fatal Case No 3
-----------------------------------	---	---	--	-----------------------

6. Mine Information :

a) Mining Company Name McElroy Coal Company	b) Mine Name McElroy Mine	c) Parent of Mining Company OHIO VALLEY RESOURCES, INC.
--	------------------------------	--

7. Mine Location :	a) City Cameron	b) County Marshall	c) State WV	8. Mine ID Number: 46-01437	9. Union: YES
--------------------	--------------------	-----------------------	----------------	--------------------------------	------------------

10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND	11. Number of Mine Employees:	a) Total 1084	b) Underground 985	c) Open Pit/Quarry 0	d) Mill/Prep Plant 99	e) Other 0
---	-------------------------------	------------------	-----------------------	-------------------------	--------------------------	---------------

12. Contractor Name:	13. Union	14. Contractor ID Number:
----------------------	-----------	---------------------------

15. Contractor Address:	a) City	b) County	c) State	d) Zip Code
-------------------------	---------	-----------	----------	-------------

16. Number of Contractor Employees:	a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
-------------------------------------	----------	----------------	--------------------	--------------------	----------

17. Number of Persons in Mine at Time of Accident:	18. Number of Persons Unaccounted For:
a) Mine Employees: 90	a) Mine Employees: 0
b) Contractor Employees: 0	b) Contractor Employees: 0

19) Location of Accident	20. Mining Height:
<input checked="" type="checkbox"/> 01-Underground	Feet Inches
<input type="checkbox"/> 02-Surface at Underground	7 0
<input type="checkbox"/> 03-Open Pit	
<input type="checkbox"/> 04-Advance Mining	
<input type="checkbox"/> 05-Mill/Prep Plant	
<input type="checkbox"/> 06-Dredge Mining	
<input checked="" type="checkbox"/> 07-Retreat Mining	
<input type="checkbox"/> 08-Office Facility	

21. Nonfatal Injuries: 3	22. Fatal Injuries: 1
-----------------------------	--------------------------

23. Victim Information :	a) Name John M. Garloch	b) Age 45
--------------------------	----------------------------	--------------

c) Regular Job Title: Assistant Longwall Coordinator	d) Activity at Time of Accident: Supervising	<input checked="" type="checkbox"/> Mine Employee
---	---	---

24. Experience :	Years Weeks Days	Years Weeks Days	Years Weeks Days	Years Weeks Days
a) Total:	12 0 0	b) at the mine:	10 0 0	c) at activity (23d):
				5 0 0
				d) with Contractor:
				0 0 0

25. Autopsy Performed: YES Ruby Memorial Hospital	26. Mine Telephone No.: (304) 686-4300
--	---

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On Sunday, March 8, 2015, at approximately 9:00 p.m., a 44 year old assistant longwall coordinator working on the 12-East longwall section was fatally injured. The victim was shoveling loose material from between the longwall face and the pan line when a large piece of rib fell from the face and pinned him on the mine floor. The rib that stuck the victim measured 12 feet long by 5 feet high by 1 foot thick. The rock was removed from the victim and he placed on a backboard and transported from the longwall face to the elevator bottom where he was evaluated by emergency medical technicians (EMT's). The victim had no pulse and attempts to administer cardiopulmonary resuscitation (CPR) and an automated external defibrillator (AED) were unsuccessful. The victim was turned over to the Cameron EMS and transported to Reynolds Memorial Hospital in Glen Dale, West Virginia where he was pronounced dead upon arrival by Harry Galloway, Paramedic. The victim was then transported to Ruby Memorial Hospital for an autopsy.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:
-----------------------------	------------

30. District: C0300 Morgantown	32. Field Office: St. Clairsville OH	33. Event Number: 6268411
-----------------------------------	---	------------------------------

34. Accident Investigator: Nicholas K. Blevins	35. MSHA Person Notified: Chad Currence	Date 03/08/2015	Time 09:11 P
---	--	--------------------	-----------------

36. Type of Report: Amended	37. Name of Preparer and Date Prepared LS for Carlos Mosley, DM	Date 04/27/2015
--------------------------------	--	--------------------

38. Reason For Amendment:  
Item 23 b) Age is 45.