

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 07/10/2015 01:30 PM		4. Date/Time of Death 07/18/2015 07:07 PM		5. Fatal Case No 12		
6. Mine Information :										
a) Mining Company Name Hanson Aggregates Midwest, LLC			b) Mine Name Dry Fork Sand & Gravel			c) Parent of Mining Company Heidelberg Cement AG				
7. Mine Location :			a) City Cleves		b) County Hamilton		c) State OH		8. Mine ID Number: 33-04460	9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 6	b) Underground 0	c) Open Pit/Quarry 0	d) Mill/Prep Plant 3	e) Other 3	
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:										
a) City			b) County			c) State		d) Zip Code		
16. Number of Contractor Employees:										
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 6		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident								20. Mining Height:		
<input type="checkbox"/> 01-Underground		<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		
<input type="checkbox"/> 02-Surface at Underground		<input checked="" type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		99-Office Facility		Feet	Inches	
21. Nonfatal Injuries: 1		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name William J. Roell					b) Age 50					
c) Regular Job Title: Superintendent				d) Activity at Time of Accident: Operating dredge				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :										
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days	
a) Total: 26 51 6			b) at the mine: 15 17 2			c) at activity (23d) 5 0 0			d) with Contractor 0 0 0	
25. Autopsy Performed: If Yes, Location YES Cincinnati, OH								26. Mine Telephone No.: (513) 367-7200		

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On Friday July 10, 2015, two miners were attempting to dislodge the clam shell bucket from the bottom of the pond when the dredge capsized. One miner was injured but was able to swim to shore and alert officials. Divers recovered the second miner from the submerged dredge on Saturday July 18, 2015.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Rohr				29. Model: 8 yd. clam shell					
30. District: M2000 Northeastern			32. Field Office: Hebron OH			33. Event Number: 6630369			
34. Accident Investigator: Michael J. Wynkoop				35. MSHA Person Notified: Joseph M. Denk		Date 07/10/2015		Time 01:48 P	
36. Type of Report: Initial			37. Name of Preparer and Date Prepared Joseph M. Denk				Date 07/20/2015		
38. Reason For Amendment:									